

Figure D.2-6. Sensitivity of magnetic field and waves measurements. The SCM and MAG together cover the full range of required measurements. SCM becomes more sensitive than MAG at ~10 Hz. The HF SCM measures z-mode, very intense radio bursts, and very fast solitary waves.