



**Figure D.2-6.** Sensitivity of magnetic field and waves measurements. The SCM and MAG together cover the full range of required measurements. SCM becomes more sensitive than MAG at  $\sim 10$  Hz. The HF SCM measures z-mode, very intense radio bursts, and very fast solitary waves.